



Release notes

MWell 19.2.2.26108

24-09-2019

Fixed bugs

DGS-608 Application does not work correctly when a dongle is inserted, while in the DS_Flex folder besides the associated dongle file also another dongle file is present for the same application.