

Release notes

D-Sheet Piling 19.3.2.28346

25-02-2020

Fixed Bugs

MSH-3564	Incorrect anchor force for step 9.1 of EC7-NL or CUR (method A) if several anchors are present (Known issue).
MSH-3577	Incorrect inputted moment given in the Report for a Single Pile calculation (Known issue).
MSH-3572	The default value of the modification factor of the sheet piling is incorrect when a new project is created (Known issue).
MSH-3570	In the summary of the Report, results from the same support is listed multiple times (Known issue).
MSH-3640	In the summary of the Report, the moment due to a support is not displayed.