

Release notes

D-Sheet Piling 19.2.3.26114

24-09-2019

Fixed bugs

DGS-608,
MINSTALL-860

Application does not work correctly when a dongle is inserted, while in the DS_Flex folder besides the associated dongle file also another dongle file is present for the same application.